

L Number	Hits	S arch T xt	DB	Tim stamp
1	100	("5247455" "5321885" "5628852" "5686702" "4587727" "4763407" "5268813" "5534666" "5590461" "4314115" "4536051" "4801876" "5512712" "5982468" "6085018" "5262954" "6021025" "4510446" "4549206" "4782283" "5325582" "5558522" "5621913" "5784484" "5909452" "6147870" "6185273" "5008619" "5821614" "4627005" "5530622" "5718038" "5743990" "6144557" "4285123" "4404059" "4628598" "4759809" "4790895" "4806957" "4863550" "5206463" "5671531" "5685071" "5710693" "5788855" "5834705" "5940964" "6053395" "6061260").pn.	USPAT; US-P PUB; EP ; JP ; DERWENT; IBM_TDB	2002/09/04 13:59

2	137246	"print d ircuit b ard"	USPAT; EP ; JP ; DERWENT; US CR USPAT; EP ; JP ; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 14:47
3	605	"print d cir uit b ard" and sch duling	USPAT; EP ; JP ; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 14:47
4	179	("printed circuit board" and scheduling) and layout	USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 14:47
6	10	((("printed circuit board" and scheduling) and layout) and assembly) and CAD	USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 14:48
5	99	((("printed circuit board" and scheduling) and layout) and assembly	USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 14:59
7	0	("printed circuit board" and scheduling) and "board arrangment"	USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:00

<b>8</b>	<b>0</b>	({"5247455" "5321885" "5628852" "5686702" "4587727" "4763407" "5268813" "5534666" "5590461" "4314115" "4536051" "4801876" "5512712" "5982468" "6085018" "5262954" "6021025" "4510446" "4549206" "4782283" "5325582" "5558522" "5621913" "5784484" "5909452" "6147870" "6185273" "5008619" "5821614" "4627005" "5530622" "5718038" "5743990" "6144557" "4285123" "4404059" "4628598" "4759809" "4790895" "4806957" "4863550" "5206463" "5671531" "5685071" "5710693" "5788855" "5834705" "5940964" "6053395" "6061260").pn. ) and "b ard arrangm nt"	<b>USPAT; EP ; JP ; DERWENT; US CR</b>	<b>2002/09/04 15:00</b>
----------	----------	---	--	-----------------------------

<b>9</b>	<b>351</b>	<b>("printed circuit board" and scheduling) and arrangement</b>	<b>USPAT; EP ; JP ; DERWENT; US CR</b>	<b>2002/09/04 15:00</b>
<b>10</b>	<b>0</b>	<b>("printed circuit board" and scheduling) and arrangement and (pcb near arrangement)</b>	<b>USPAT; EP ; JPO; DERWENT; USOCR</b>	<b>2002/09/04 15:01</b>
<b>11</b>	<b>6</b>	<b>("printed circuit board" and scheduling) and arrangement) and (board near arrangement)</b>	<b>USPAT; EPO; JPO; DERWENT; USOCR</b>	<b>2002/09/04 15:02</b>
<b>12</b>	<b>31395</b>	<b>700/\$.ccls.</b>	<b>USPAT; EPO; JPO; DERWENT; USOCR</b>	<b>2002/09/04 15:03</b>
<b>13</b>	<b>48</b>	<b>("printed circuit board" and scheduling) and 700/\$.ccls.</b>	<b>USPAT; EPO; JPO; DERWENT; USOCR</b>	<b>2002/09/04 15:12</b>
<b>14</b>	<b>222473</b>	<b>29/\$.ccls.</b>	<b>USPAT; EPO; JPO; DERWENT; USOCR</b>	<b>2002/09/04 15:13</b>

15	17	<p><b>29\$/ccls. and (("5247455"</b></p> <p><b>"5321885"</b></p> <p><b>"5628852"</b></p> <p><b>"5686702"</b></p> <p><b>"4587727"</b></p> <p><b>"4763407"</b></p> <p><b>"5268813"</b></p> <p><b>"5534666"</b></p> <p><b>"5590461"</b></p> <p><b>"4314115"</b></p> <p><b>"4536051"</b></p> <p><b>"4801876"</b></p> <p><b>"5512712"</b></p> <p><b>"5982468"</b></p> <p><b>"6085018"</b></p> <p><b>"5262954"</b></p> <p><b>"6021025"</b></p> <p><b>"4510446"</b></p> <p><b>"4549206"</b></p> <p><b>"4782283"</b></p> <p><b>"5325582"</b></p> <p><b>"5558522"</b></p> <p><b>"5621913"</b></p> <p><b>"5784484"</b></p> <p><b>"5909452"</b></p> <p><b>"6147870"</b></p> <p><b>"6185273"</b></p> <p><b>"5008619"</b></p> <p><b>"5821614"</b></p> <p><b>"4627005"</b></p> <p><b>"5530622"</b></p> <p><b>"5718038"</b></p> <p><b>"5743990"</b></p> <p><b>"6144557"</b></p> <p><b>"4285123"</b></p> <p><b>"4404059"</b></p> <p><b>"4628598"</b></p> <p><b>"4759809"</b></p> <p><b>"4790895"</b></p> <p><b>"4806957"</b></p> <p><b>"4863550"</b></p> <p><b>"5206463"</b></p> <p><b>"5671531"</b></p> <p><b>"5685071"</b></p> <p><b>"5710693"</b></p> <p><b>"5788855"</b></p> <p><b>"5834705"</b></p> <p><b>"5940964"</b></p> <p><b>"6053395"</b></p> <p><b>"6061260").pn.</b></p> <p>)</p>	<p><b>USPAT;</b></p> <p><b>EPO; JPO;</b></p> <p><b>DERWENT;</b></p> <p><b>US CR</b></p>	<p><b>2002/09/04</b></p> <p><b>15:15</b></p>
----	----	--	---	--

16	0	"Gerber adj Garment"	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:15
17	541	rb r adj Garment	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:15
19	0	((Gerber adj Garment) and waste) and "waste minimization"	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:16
18	55	(Gerber adj Garment) and waste	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:21
20	185	cutting near "circuit boards"	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:22
21	8	(cutting near "circuit boards") and waste	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:26
22	0	(cutting near "circuit boards") and scheduling	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:26
23	0	(cutting near "circuit boards") and scheduling	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:26
24	34	(cutting near "circuit boards") and production	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:30
25	837	PCB near manufacturing	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:30
26	390	(PCB near manufacturing) and (printed near circuit)	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:31
27	70	((PCB near manufacturing) and (printed near circuit)) and cut	USPAT; EPO; JPO; DERWENT; USOCR	2002/09/04 15:37
28	204	"printed wiring board assemblys"	USPAT; EP ; JP ; DERWENT; USOCR	2002/09/04 15:39

29	63	"printed wiring board assemblies" and manufacturing	USPAT; EP ; JPO; DERWENT; US CR USPAT; EP ; JPO; DERWENT; USOCR USPAT; EPO; JPO; DERWENT; USOCR USPAT	2002/09/04 15:39
30	4	("printed wiring board assemblies" and manufacturing) and "manufacturing system"	USPAT; EP ; JPO; DERWENT; USOCR USPAT	2002/09/04 15:43
31	10	"5321885"	USPAT; EPO; JPO; DERWENT; USOCR USPAT	2002/09/04 15:44
32	14	5516028.URPN.	USPAT	2002/09/04 15:51
33	23	("3421211"   "3803556"   "4256296"   "4504919"   "4564102"   "4604704"   "4694570"   "4706187"   "4719694"   "4731567"   "4759488"   "4821197"   "4850104"   "4980970"   "5067648"   "5086557"   "5170554"   "5268849"   "5321885"   "5335601"   "5355579"   "5536128"   "5680696").PN.	USPAT	2002/09/04 15:58